# D11-North Auxiliary Operations Training Officer AUXILIARY ANTI-EXPOSURE COVERALL SEMI-ANNUAL INSPECTION Revised March 2014

This job aid is intended to assist Auxiliary Rescue and Survival inspectors. It is a supplement to U.S. Coast Guard Maintenance Procedure Cards and should be used in conjunction with the referenced MPCs to complete semi-annual inspections and test.

Ref: (a) MPC RSS583023.0, Standard Issue PPE Acceptance Inspection, 7/3/13.

## A. Inspect anti-exposure coveralls:

- 1. Lay out the coveralls in a clean area free of obstructions.
- 2. Inspect the coveralls for the following:
  - a. Check for cuts, tears, seam separation or loose stitching.
  - b. Check entry/leg zippers for operability.
  - c. Check for U. S. Coast Guard Auxiliary markings.
  - d. Check condition of installed reflective tape.
- 3. Remove anti-exposure coveralls from service and contact the OTO if any of the above items are found discrepant.

# B. Leak test head pillow as follows:

#### **WARNING**

AVOID EYE CONTACT, INHALATION, AND PROLONGED SKIN CONTACT WITH LEAK TEST COMPOUND. USE IN A WELL VENTILATED AREA. FAILURE TO COMPLY MAY RESULT IN PERSONAL INJURY.

- 1. Remove inflatable head pillow bladder from cover.
- 2. Inflate head pillow through the oral inflation tube until firm.
- 3. Apply leak test compound provided by the OTO to the entire head pillow surface.
- 4. Inspect head pillow for signs of leakage.
- 5. Remove anti-exposure coveralls from service and contact the OTO if the head pillow is leakage is found.
- 6. Deflate head pillow through inflation tube.
- 7. Place deflated head pillow back into cover.
- 8. Ensure oral inflation tube is pulled out, readily accessible.

### C. Clean Anti-Exposure Coveralls:

#### Caution:

DO NOT DRY ANTI-EXPOSURE COVERALLS USING A MACHINE DRYER,
HEATER OR IRON. HEAT WILL DAMAGE THE SUIT

1. Clean Anti-Exposure coveralls as follows:
<ul><li>a. Hand wash the coveralls inside and out using a mild detergent, such as dish soap or Simple Green.</li><li>b. Rinse the coveralls with fresh water.</li><li>c. Hang dry coveralls, recommend drying inside out first, then turning right side out.</li><li>d. Lubricate zippers using paraffin wax.</li></ul>
D. Restore individual serial number marking under the entry zipper cover near the top, if faded or unreadable.
E. Document semi-annual inspection in the PPE Maintenance Log. Notify the OTO of any discrepancies.
Page 2 of 2